

Sheet (6)  
CNC M/C Tools  
Part program – Turning Machine


---

3- It is required to produce the workpieces show in the figures below . The machine used is a CNC turning machine has the following format:-

**N5 G3 X±3.3 Z±3.3 I±3.2 K±3.2 F4 S4 T4 M2**


- Suggest the required tooling for machining each part in a form of table and the proper machining values.
- Construct the part program.
- Calculate the production rate give that :
  - the ATC (automatic tool changer) capacity is 12 –station, and indexing time is 0.45s
  - the rapid traverse speed is 600 m/min.

A)




Workpiece Material is free cutting brass bar with 6 m length and 10 mm diameter.

B)




Workpiece Material is free cutting brass bar with 6 m length and 40 mm diameter.

C)



Workpiece Material is free cutting brass bar with 6 m length and 25 mm diameter.

D)



workpiece made from free cutting brass bar with 6 m length and a 70 mm diameter

- Notes:** The Machine uses
- G53 for Zero Offset off
  - G54 for Zero Offset #1
  - G55 for Zero Offset #2
  - G56 for Zero Offset #3
  - G57 for Zero Offset #4
  - G58 for Zero Offset #5
  - G59 for Zero Offset #6

## Description of G Commands

### G00 Positioning (Rapid Traverse)

#### Format

N.... G00 X(U)... Z(W)...

The slides are traversed at maximum speed to the programmed target point. Incremental and absolute commands can be used at the same time.

#### Note

- A programmed feed F will be suppressed while G00.
- The maximum feed is defined by the producer of the machine.
- The feed override switch is limited to 100%.


#### Example

##### absolute G90

N50 G00 X40 Z56

##### incremental G91

N50 G00 U-30 W-30.5



Absolute and incremental measures for G00

### G01 Linear Interpolation (Feed)

#### Format

N... G01 X(U)... Z(W)... F....

Linear slide movements (face, longitudinal, taper turning) at the programmed feedrate.

#### Example

##### absolute G90


N.. G95

.....  
N20 G01 X40 Z20.1 F0.1

##### incremental G91

N.. G95 F0.1

.....  
N20 G01 X20 W-25.9



Absolute and incremental measures for G00