


Assignment 2 (maximum 2 per group): How to use PolyMUMPs process? **Due on Monday 23/3/2015 @3:00 pm**



1. Use PolyMUMPs process to implement the shown device
2. Modify the shown dimension to be compliant with PolyMUMPs
3. Draw the process masks
4. Draw a cross section for the fabricated structure before release

Assignment:

1. Repeat step 1-4, If the dimension is 3.7μm and 5μm

